



CHAPA PERFORADA CUADRADOS


3 mm.




4 mm.




5 mm. F




5 mm.




8 mm.




10 mm. F




10 mm.




12 mm.



15 mm.



19 mm.



20 mm.





Lado	Distancia centros	Grueso en mm.	Coefficiente perforación
3	5	0,5 a 1,5	36
4	7	0,5 a 1,5	36
5 F	7	0,5 a 1,5	51
5	8	0,5 a 2	39
6	9	0,5 a 2	44
8	11,3	0,5 a 2	50
10 F	12,8	0,5 a 2,5	61

Lado	Distancia centros	Grueso en mm.	Coefficiente perforación
10	15	0,5 a 3	44
12	17	0,5 a 3	41
15	20	0,5 a 3	49
19	22,2	0,5 a 1,5	73
20	25	0,5 a 2	64
20	27	2,5 a 3	55
30	35	0,5 a 2	73

CHAPA PERFORADA CUADRADOS


30 mm

40 mm.



Lado	Distancia centros	Grueso en mm.	Coefficiente perforación
30	38	2,5 a 3	62
40	50	1 a 3	64

CUADRADO DECORATIVO



Lado	Distancia centros	Grueso en mm.	Ancho máximo	Largo máximo
20	40	1 a 4	1250	5000