



PERFILES DE ACERO

SIMPLES T



Descripción	B	H	s=t	kg/m
T	25	25	3,5	1,29
T	30	30	4	1,77
T	35	35	4,5	2,33
T	40	40	5	2,96
T	45	45	5,5	3,67
T	50	50	6	4,44
T	60	60	7	6,23
T	70	70	8	8,32
T	80	80	9	10,70
T	100	100	11	16,40

UPN PERFILES U PEQUEÑOS



Designación	kg/m	Dimensiones (mm)				m ² /m
		h	b	a	e	
U 30x15	1,74	30	15	4	4,5	0,103
U 40x20	2,87	40	20	5	5,5	0,142
U 40x35	4,87	40	35	5	7	0,199
U 50x25	3,86	50	25	5	5	0,181
U 50x38	5,59	50	38	5	7	0,232
U 60x30	5,07	60	30	6	6	0,215
U 65x42	7,09	65	42	5,5	7,5	0,273
U 70x40	6,77	70	40	6	6,5	0,276